

General Environmental Incident Summary

Incident: 5540 **Notice:** 10/4/2017 1441 **Occurred:** 10/4/2017 1230

DEM Incident No:

No Further Action: ☒

Responsible Party: Sanitary Septic Services

County: Burleigh

Twp Rng Sec Qtr: 139 79 36

Lat Long + Method: 46.81136 -100.59850 Interpolation from map

Location Description: Doug Sailer, 624 Grassy Meadow Pl., Menoken, ND. East on highway 10 from Bismarck, South on 119th street, East on Country Meadow Dr, North on Grassy Meadow Pl.

Submitted By Info: Leo Ternes
Owner
17092 33rd St NE
Baldwin ND 58521

Received By Info:

Contact Info: Leo Ternes
17092 33rd Street NE
Baldwin ND 58521

Affected Medium: 03 - soil

Near. Occupied Bldg: 20 Feet

Type of Incident: Sewage Accident

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Septic water

Volume of Release: 15 gallons

Duration of Release: 1 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Hose came out of clean-out pipe while pumping as I was going to turn off valve. Water spilled out before valve could be closed.

Spilled mostly in grass and dirt around tank area.

Risk Evaluation:

No immediate risk.

Potential Env. Impacts:

Don't believe there should be any soil impact.

Wet for an hour or so.

Action Taken/Planned:

Reversed pump, and sucked up all the septic water back into hose as best we could.

Took garden hose and rinsed off and watered down the grass and dirt to rinse off grass.

Future action: Watch hose more closely. Try and weight down hose if possible.

Wastes Disposal Location:

JS1 dump site.

Other Agencies Involved:

Updates

Date: 10/4/2017 ***Status:*** Reviewed - Assigned to NDDEQ Division

Author: O'Gorman, Brian

Notes:

According to the report, 15 gallons of septic water was released onto site soils. Incident assigned to Division of Water Quality for oversight.

Updated Volume: None at the time of this update